
Installation Guide (Windows 7 64 bit) - U204FB-A1

Certificate making for Windows 7 64 bits

Procedure

- 1. Logged in with administrative privileges.
- 2. Diasble UAC User Access Control


Go to "Control Panel"




Go into "User Accounts and Family Safety"




Go into "User Accounts"



Click "Change User Account Control settings"




Tune to "Never notify"




- 3. Unzip the LCD2USB.zip file (If CD-ROM is not provided).
- 4. Copy the folder "lcd2usbdriver" to any drives and folders you like.
- 5. Copy the folder "dseo13b Driver Signature Enforcement Overrider" to any drives and folders you like.
- 6. Double click to run the "Driver Signature Enforcement Overrider"




7. Click "Next".




8. Click "Yes".



9. Select "Sign a System File" and click "Next".



10. You need to sign the driver "libusb0_x64.sys" in folder of lcd2usbdriver. Insert a driver filename "libusb0_x64.sys" including full path where it located and click "OK".




11. The driver has been singed and click "OK".



12. Select "Enabled Test Mode" and click "Next".




13. Test Mode has been ENABLED.



14. After restart your computer, you will see "Test Mode" at corner of screen.



15. Run "RemoveWatermarkX64" to remove those water mark.



16. Type "Y" and press enter.


17. Water marks have been removed.

```
_ - ×
Remove Watermark x86
                     Windows Vista /Server 2008 /Windows 7, 32bit(x86)
All Service Pack & all language of Windows.
       Support:
       Author:
Blog:
                      deepxw
http://deepxw.lingd.net
http://deepxw.blogspot.com
                                                                (English)
Please right click the exe file, run as administrator.
    you really want to apply this patch?
/=Yes / N=No / R=Rebuild MUI Cache by mcbuilder.exe)
  File Name: C:\Windows\System32\en-US\user32.dll.mui V6.0.6000.16386 (x86)
    ID
        String
                                                                                           Offset
                                                                                                       Len Mod
         ZwsWindows Xws
Xws Build Xws
Evaluation copy.
For testing purposes only.
Test Mode
XwsMicrosoft (R) Windows (R) (Build Xws: Xws)
This copy of Windows is not genuine
                                                                                                        28
26
32
52
18
90
70
File has been patched:
Re-checksum the file:
Backup the file:
Overwrite old file:
                                                     Backup file name: user32.dll.mui.backup
After reboot, if the watermark still exists, you can munally run mcbuilder.exe and reboot again.
???,???????,???????mcbuilder.exe,???
Log off, or restart your computer to take effect!
??????????
Press Enter to exit.
```

18. Tune back your UAC User Access Control level.



19. Click "Restart Now".




Driver and Hardware Installation for Windows 7 64 bit

Procedure

Please do "Certificate making for Vista 64 bits first".

1. Prepare the USB connection to U204MB-A1.

You can use internal USB connection (CN4)or external USB connection (CN2)



Plug in the internal USB cable to CN4 (Red-VBus/VCC, White-D-, Green-D+, Black-GND)



2. Filing the plastic cushion of your PC case by sand paper or file. That's can make the frame can fit into bay drive.



3. Insert the frame into the bay drive.



4. Peel off the protective layer of LCD.



5. Stick the cover sheet on the front end of frame carefully.




6. Mount those bay drive screws.




7. Peel off the protective layer of cover sheet. Outlook like this.



8. Power off your PC first and then find your internal USB port in your mother board.




9. Plug the internal USB cable to your board. Please reference the pins configuration of mother board user manual.



- 10. For internal USB cable has been connected, power up your PC.
- 11. Firmware message will be shown on the LCD.




12. "Device driver software was not sucessfully installed". will be popup on screen."




13. Go to Control Panel




14. Choose "Hardware and Sound"




15. Click "Device Manager" in "Devices and Printers"




16. Find "LCD2USB" in Other devices.




17. Right click to go into "Properties" and choose "Update Driver Software".




18. Click "Browse my computer for driver software"



19. Browse the folder "lcd2usbdriver" where the driver is located and click "OK".




20. Select the driver folder "Icd2usbdriver". and click "Next"



21. "Install this driver software anyway"



22. Wait for the driver installation, then click "Close".



23. The driver of this device has been successfully installed and device is ready to use.


Configuration in LCD Smartie

Procedure


1. Copy the whole folder "lcd.smartie-v5.4" to any folder/driver of your PC and click into the folder and run "LCDSmrtie".



2. Click in the setup and make sure Display Plugin is "LCD2USB.dll".



3. Set the screen according to your LCD. LCD contrast and backlight brightness can be tune here.



3. Finished. LCD Smartie information is shown on the LCD now.

